

IRON SHAFT BEND PROFILE CHART			
SHAFT MODEL	BUTT SECTION	MID SECTION	TIP SECTION
TOUR AD 50g L Flex	MEDIUM	SOFT	SOFT
TOUR AD 55g R & S Flex	MEDIUM	MEDIUM	SOFT
TOUR AD 65g R & S Flex	FIRM	MEDIUM	SOFT
TOUR AD 75g R & S Flex	FIRM	MEDIUM	SOFT
TOUR AD 85g R & S Flex	STIFF	FIRM	MEDIUM
TOUR AD 95g S & X Flex	STIFF	FIRM	FIRM
TOUR AD 105g S/X Combo	STIFF	STIFF	FIRM
TOUR AD 115g S/X Combo	STIFF	STIFF	FIRM
TOUR AD DI UT Driving Iron 85g S Flex	STIFF	FIRM	MEDIUM
TOUR AD DI UT Driving Iron 95g S & X Flex	STIFF	FIRM	FIRM
TOUR AD VF UT Driving Iron 95g S & X Flex	STIFF	STIFF	VERY STIFF
TOUR AD VF UT Driving Iron 105g S & X Flex	STIFF	STIFF	VERY STIFF
RAUNE 60g R Flex	MEDIUM	SOFT	SOFT
RAUNE 75g R Flex	MEDIUM	MEDIUM	SOFT
RAUNE 90g Stiff Flex	FIRM	MEDIUM	MEDIUM
RAUNE 105g S & X Flex	FIRM	FIRM	FIRM
LEGEND DESCRIBING THE SHAFT STIFFNESS FROM STIFFEST TO SOFTEST: VERY STIFF → STIFF → FIRM → MEDIUM → SOFT			